

10/7/15

MY 15 DS & DJ Pickup

GPOP - Issue Review System

Part Number: 1NN14DX9A\$, 1NN14HL1A\$, 5NB15DX9A\$, 5RQ83DX9A\$

Part Description: FLOOR CONSOLE ASSEMBLY

Issue Description: Please follow this procedure to resolve Center Floor Console noise (e.g. ticking, buzz, squeak, rattle):

1) Remove tape/film from the Center Floor Console latch areas (Arm Rest Lid latch {Upper compartment} & bezel and Storage Bin {lower compartment} latch & bezel surfaces).

2) Apply interior cleaner onto cloth to remove the tape/film adhesive from the plastic latch & bezel and Storage Bin & Armrest Lid contact surfaces.

Verify problem is resolved.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
