



SI B13 03 15
Fuel Systems

April 2015
Technical Service

SUBJECT

N20 and N26 Engines: ETK Injector Part Number Error

MODEL

E84 (X1)

E89 (Z4)

F10 (5 Series Sedan)

F22 (2 Series Coupe)

F25 (X3)

F30 (3 Series Sedan)

F31 (3 Series Sports Wagon)

F32 (4 Series Coupe)

F34 (3 Series Gran Turismo)

F36 (3 Series Gran Coupe)

INFORMATION

The current version of ETK has an error on screen 13_1417: "High -pressure pump/Tubing."

When selecting the high-pressure pump, the screen states "only in conjunction with injector." **Disregard this statement and only replace the high-pressure pump.**

If injectors need to be replaced, enter the VIN of the vehicle into the ETK and select the part numbers found on screen 13_1416: "High-pressure rail/injector/mounting."

Always enter the VIN for the vehicle into ETK when searching for parts.

When the ETK is corrected, this SIB will be updated.

WARRANTY INFORMATION

Not applicable.

[Copyright ©2015 BMW of North America, Inc.]