



## SUBJECT

**Google™ Local Search Inactive**

## MODEL

E84 (X1)

E89 (Z4)

Produced from March 2013


With option 609 (Navigation System Professional)

and

With option 6AE (BMW TeleService)

## SITUATION

When searching for a Point of Interest (POI) in the navigation menu, the “Google™ Local Search” option cannot be selected.



## CAUSE

The POI search option “Google™ Local Search” is not activated.

## CORRECTION

**Do not replace parts, and do not program or code the vehicle.**

Activate “Google™ Local Search” by performing a BMW ASSIST update in the vehicle, using the iDrive controller.

## PROCEDURE

1. Select the “ConnectedDrive” menu from the main menu.
2. Select “Service Status” from the ConnectedDrive list. Push the iDrive controller down to access this submenu.



3. Select “Update BMW Assist.”
4. Click to start the BMW ASSIST update.

**WARRANTY INFORMATION**

Not applicable.

[ Copyright ©2015 BMW of North America, Inc. ]