



SI M25 01 14 Gear Shift Mechanism

April 2015
Technical Service

This Service Information bulletin supersedes SI M25 01 14 **dated July 2014**.

NEW designates changes to this revision

SUBJECT

NEW Manual Gear Shift Knob Loose

MODEL

F56 (Hardtop)

NEW Produced from December 2013 to August 2014

SITUATION

The manual transmission gear shift knob easily comes off the shift rod with minimal upward force.

CAUSE

The retaining tabs on the shifter knob do not hold securely to the shifter rod.

NEW PROCEDURE

Replace the shift knob. Refer to Repair Instruction RA 25 11 071, "Replacing gearshift lever knob."

NEW PARTS INFORMATION

Part Number	Description	Quantity
25 11 7 641 999	Shift knob	1

WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty.

Defect Code:	25 11 03 37 00	
Labor Operation:	Labor Allowance:	Description:
25 11 071	Refer to KSD2	Replace shift knob

Labor operation code 25 11 071 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation 25 11 571 instead.

[Copyright ©2015 BMW of North America, Inc.]