

April 2015 Technical Service

SUBJECT Delivery Stop: Remove Engine Oil Label

MODEL

F55 (Cooper 4-Door Hardtop, Cooper S 4-Door Hardtop)

F56 (Cooper 2-Door Hardtop, Cooper S 2-Door Hardtop, JCW Hardtop 2-Door)

SITUATION

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be remedied prior to dealer delivery.

On affected vehicles, there is an incorrect label regarding the appropriate engine oil.

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Vehicle Inquiry or ISPA Light.

CAUSE

The text on the label does not conform to legal regulations.



CORRECTION

Remove the label.

PROCEDURE

Remove the label using a hot air gun to soften the adhesive. Gently pull the label off while varying the heat. Remove any remaining adhesive with a solvent-based cleaner.

Discard the removed label.

WARRANTY INFORMATION

The flat rate unit (FRU) allowance amount below is for repair order invoicing only.

Defect Code:	00 71 20 02 00	
Labor Operation:	Labor Allowance:	Description:

TBD 1 FRU Remove engine oil label	
-----------------------------------	--

Please do not submit your claim until the final labor operation number for claim submission is provided with the reissue of this Service Information bulletin.

ADDITIONAL INFORMATION

Perform the procedure outlined in this Service Information on all affected vehicles before customer delivery or the next time they are in the shop for maintenance or repairs.

[Copyright ©2015 BMW of North America, Inc.]