

11/4/15

MY14 WK

GPOP - Issue Review System

Part Number: 5QX861W1A\$, 5QX851S5A\$, 5QX871L1A\$, 5QX951SFA\$

Part Description: Leather Instrument Panel

Issue Description: If replacing the instrument panel top cover because of what appears to be a wrinkle or thread in the leather near the A-pillar, then please call Mike Wicker at Cell (248) 821-9350. Chrysler wants to learn more about these conditions. A photo of the condition would be beneficial and can be sent to MDW12@chrysler.com. If no response is received within 15 minutes, then proceed with the required repair.

~ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
