

11/4/15

MY15 LD, PF, WD, WK, UF

GPOP - Issue Review System

Part Number: 68082477A\$, 68250107A\$

Part Description: Motor, Sunroof

Issue Description: If looking to replace the sunroof motor and these conditions are occurring:~
1) Vent switch does not work.~
2) Open switch only moves the sunroof an inch no matter how long the switch is held.~
3) When the close switch is used, sunroof closes but then goes into vent.~
The sunroof motor does not need to be replaced, but only reinitialized. Please follow reinitialization procedure available in TechCONNECT.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
