

11/24/15

MY 14, 15

WK, WL

GPOP - Issue Review System

Part Number: 5QV32DX9A\$, 5QM91DX9A\$, 5QV28DX9A\$, 5QV30DX9A\$

Part Description: WHEEL - STEERING

Issue Do not replace Steering Wheel due to heating temperature concern.~

Description: Engineering is working on software update to address this customer concern.~

~

~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.