



NUMBER: 14-002-15

GROUP: Fuel System

DATE: December 10, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-121. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Fuel Filler Tube

OVERVIEW:

This bulletin involves replacing the fuel tank fill tube due to an incorrect part specification.

MODELS:

2016 (MK74) Jeep Patriot

**NOTE: This bulletin applies to vehicles within the following markets/countries:
NAFTA**

NOTE: This bulletin applies to MK74 vehicles built on or after September 14, 2015 (MDH 0914XX) and on or before September 18, 2015 (MDH 0918XX).

SYMPTOM/CONDITION:

Some fuel tank filler tubes may have an issue with the fuel cap thread specification.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
(1)	05105255AF	Tube, Fuel Filler

REPAIR PROCEDURE:

1. Tighten the fuel cap and listen for 2 clicks.
2. Does the fuel cap remain secured or tightened?
 - a. YES>>> This bulletin has been completed, use LOP (14-60-15-9A) to close the active RRT.
 - b. NO>>> Proceed to [Step #3](#).
3. Remove and replace the fuel tank filler tube. Refer to 14 - Fuel System/Fuel Delivery, Gas/Tube, Fuel Tank Filler/Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
14-60-15-9A	Cap, Fuel Cap On Filler Tube (Inspection Only) (1 - Semi-Skilled)	8 - Engine Performance	0.2 Hrs.
14-60-15-9B	Tube, Fuel Tank Filler Replace (1 - Semi-Skilled)	8 - Engine Performance	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------