



V-15-07-01

VOICE of



July 1, 2015

Published for Victory Dealers, Distributors, and Service Staff


SUBJECT: VICTORY MAGNUM, X-1 - REPROGRAMMING (REFLASH) PROCEDURE

MODELS: MAGNUM, X-1

Victory Motorcycles has determined the reprogramming (reflash) procedure may be negatively affected if performed with a device connected to the USB connector.

It is important to disconnect all devices from the USB connector ① prior to performing an ECM, ABS Controller or Audio System reprogramming (reflash) procedure.

A technician should be familiar with Digital Wrench® and computer operation in general before attempting any reprogramming (reflash) procedure. Refer to the appropriate Victory Service Manual for additional information.



****Please distribute to dealership personnel as required****