

SERVICE CAMPAIGN BULLETIN

CAMPAIGN REF: 037

TITLE : McLaren P1™ US Emissions Label Correction


DOCUMENT # : 12 P 001

AFFECTED VEHICLES : McLaren P1™

SITUATION : Quality Engineering at McLaren Automotive have identified that a number of vehicles have been fitted with VECI (US Emission) label which has a typing error on them.

PROCEDURE : It is necessary to replace the current VECI label with the new label with the correct reference on. Please follow the instructions outlined in this document.

1. Push down and then lift up the service tray access panel on the passenger's side of the roof.
2. Remove the existing VECI (US Emission) label (1).



3. Clean the surface with an alcohol cleaning solution or similar product to remove any dirt.
4. Install the new label 12P0197CP where the old label was installed.

Please contact your Regional Aftersales Manager should you have any questions relating to the information contained in this bulletin.

WARRANTY INFORMATION

DESCRIPTION	RESOLUTION CODE	TOTAL REPAIR TIME
US Emission Label Correction	BCAT0197A26B9904	0.2 hrs

PARTS INFORMATION

PART DESCRIPTION	PART NUMBER	QUANTITY	ORDER PROCESS
LABEL-VCL-EMISS-USA-2013MY	12P0197CP	1	Unipart
