

IMPORTANT SAFETY RECALL INTERIM NOTICE



565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

February 17, 2015

Re: Can-Am® Spyder® Roadster RT™ 2013 – Elevated Temperature in Engine Compartment

Dear Can-Am roadster Dealer,

This interim notice is being sent to you in accordance with the requirements of the National Traffic Motor Vehicle and Canada Motor Vehicle Safety Acts. BRP has decided that a defect which relates to motor vehicle safety exists on certain Can-Am roadster models.

What is the potential problem?

Under very hot ambient conditions and low speed riding, the temperature in the engine compartment may rise and thereby increase the risk of a skin burn or a vehicle fire.

Which models are involved?

Can-Am Spyder RT roadster, model year 2013.

What will BRP do?

BRP intends to repair involved vehicles, free of charge for the customer (parts and labor). However, the parts required to provide a remedy to this condition are not currently available and will become available starting in May 2015. Nevertheless, we wanted to contact you as quickly as possible to inform you of this safety recall.

For dealers: BRP will contact you with another letter when the remedy is available in your area, so you have all instructions to follow for this safety campaign. Please understand that we will prioritize the hottest areas of the countries as parts become available.

For customers: BRP will be sending to all known registered owners an interim notice.

Also, BRP is posting this notice on its dealer website BOSSWeb (www.bossweb.brp.com). Information for customers is posted on BRP's public website (www.can-am.brp.com).

What should you do?

Inform involved vehicle owners that they can keep using their vehicle while taking the following precautions in hot riding conditions (ambient temperature of approximately 30 C/85 F and more):

- Avoid idling or slow traffic riding for a long period of time.
- Avoid parking in an enclosed area immediately after your ride, let your vehicle cool down first.
- Avoid prolonged direct contact with body panels; wear appropriate riding gear as stated in the Operator's Guide.

For unsold vehicles at your dealership (new or used):

Inform new owners of involved vehicles of the foregoing. You must supply the manufacturer's copy of the *Owner Safety Recall Interim Notice*, and explain that they can use their vehicle as per the 3 precautions (described here over and in the *Owner Safety Recall Interim Notice*).

Ski-Doo
Lynx
Sea-Doo
Evinrude
Rotax
Can-Am

If you have questions about this notice, please communicate with us:

- By submitting a **BOSSWeb case**. A service representative will communicate with you.

OR

- In USA and Canada: [1-800-366-6992](tel:1-800-366-6992)
Eastern time Monday to Friday from 10:00 AM to 5:00 PM

Thank you for your immediate attention to this matter.

Sincerely,
After-Sales Service Department

IMPORTANT SAFETY RECALL INTERIM NOTICE

This notice applies to your vehicle



565 de la Montagne Street
Valcourt, Québec, Canada J0E 2L0
T 450.532.2211 F 450.532.5133

www.brp.com

February 26, 2015

Re: Can-Am® Spyder® Roadster RT™ 2013 – Elevated Temperature in Engine Compartment

Dear Can-Am Spyder RT 2013 Owner,

This interim notice is being sent to you in accordance with the requirements of the National Traffic Motor Vehicle and Canada Motor Vehicle Safety Acts. BRP has decided that a defect which relates to motor vehicle safety exists on certain Can-Am roadster models.

Our records show that you own a potentially affected vehicle.

What is the potential problem?

Under very hot ambient conditions and low speed riding, the temperature in the engine compartment may rise and thereby increase the risk of a skin burn or a vehicle fire.

Which models are involved?

Can-Am Spyder RT roadster, model year 2013.

What BRP will do?

BRP intends to repair your vehicle free of charge (parts and labor). However, the parts required to provide a remedy to this condition are not currently available and will become available starting in May 2015. Nevertheless, we wanted to contact you as quickly as possible to inform you of this safety recall. BRP will contact you with another letter when the remedy is available in your area, instructing you to make an appointment with your BRP Can-Am Roadster dealer. Please understand that we will prioritize the hottest areas of the countries as parts become available.

What should you do until your vehicle is repaired?

You can keep using your vehicle while taking the following precautions in hot riding conditions (ambient temperature of approximately 30 C/85 F and more):

- Avoid idling or slow traffic riding for a long period of time.
- Avoid parking in an enclosed area immediately after your ride, let your vehicle cool down first
- Avoid prolonged direct contact with body panels; wear appropriate riding gear as stated in the Operator's Guide.

What to do if you feel this notice is an error?

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please contact BRP at your earliest convenience.

Ski-Doo
Lynx
Sea-Doo
Evinrude
Rotax
Can-Am

For US residents only

If you believe that BRP has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E. Washington, D.C. 20590, or call the toll free Auto Safety Hot Line at 1- 888-327-4236 (TTY: 1-800-424-9153), or go to www.safercar.gov. If you are a vehicle lessor, federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Your continued satisfaction with your roadster is important to us. We have taken this action in the interest of your safety and your vehicle's proper operation. We apologize for any inconvenience this may cause you and appreciate your patience while we prepare the remedy for this condition. If you have questions or need assistance:

- Visit www.can-am.brp.com
- Or call: 1-888-272-9222
9:00 AM to 9:00 PM Eastern time Monday to Friday

Sincerely,
After-Sales Service Department