



WARRANTY BULLETIN

Quality

NOTE: Repair only if described symptoms exist or are noticed.

Campaign no.: 2014-0011
2015-0004

July 9, 2015

Subject: **Insufficient Parking Brake Cable Tension When Applied**

No. **2015-5**

YEAR	MODEL	SERIAL NUMBER
2014	RT	All
2015		Search serial # on <i>KNOWLEDGE CENTER</i>


PROBLEM

The parking brake motor may not apply/hold enough tension on the brake cable.

SOLUTION

Replace the parking brake motor with the *REQUIRED PART*. Follow the procedure in the 2013 Roadster *SHOP MANUAL, BRAKES* subsection.

REQUIRED PART



Order part through the regular channel.

DESCRIPTION	PART NUMBER	QUANTITY
Parking brake motor	278 003 071	1

WARRANTY

Submit a warranty claim using the following information.

Click in the *REPAIR* check box while completing your claim on BOSSWeb.



The screenshot shows a web form interface. At the top, there is a label '*Action'. Below it, there are two checkboxes: 'Inspect' and 'Repair'. An arrow points to the 'Repair' checkbox. Below the checkboxes is an 'Upload File' button. The text 'mbg2012-010-004_ben' is visible at the bottom left of the screenshot.

For claiming procedure, refer to the *DEALER/DISTRIBUTOR WARRANTY GUIDE*.

<i>CAMPAIGN NUMBER</i> 2014 Models	2014-0011
<i>CAMPAIGN NUMBER</i> 2015 Models	2015-0004
Claim Type	Campaign Claim
Action	Repair
Flat Rate Time	1.0 hour