



WARRANTY BULLETIN

Warranty Campaign

CAN-AM® ROADSTER

CAUTION: All involved customers must be notified, all involved units must be corrected as per instruction herein.

Campaign no.: 2015-0005

July 21, 2015

Subject: **Gearbox Position Sensor Contamination**

No. **2015-7**

YEAR	MODELS	SERIAL NUMBER
2015	Spyder F3 and RT	See warranty campaigns in Knowledge Center

PROBLEM

A limited quantity of vehicles were shipped with liquid contaminants in the gearbox position sensor (GBPS) housing that will damage the sensor.

A damaged GBPS may lead to; P-codes, limp home mode activation or vehicle does not shift.

SOLUTION

Replace GBPS and clean its housing.

PART REQUIRED

Order part through regular channel.

DESCRIPTION	PART NUMBER	QTY
Gearbox Position Sensor (GBPS)	420265120	1


PROCEDURE

Refer to appropriate electronic shop manual on Knowledge Center for the most up to date procedure.

NOTICE Make sure to clean and dry all dust and liquid contaminants on the crankcase before the installation of the new GBPS.



GBPS



GBPS HOUSING

WARRANTY

Submit a warranty claim using the following information:

For claiming procedure, refer to the *DEALER/DIS-TRIBUTOR WARRANTY GUIDE*.

CAMPAIGN NUMBER	2015-0005
Claim Type	Campaign Claim
Action	Repair
Flat Rate Time	1 hour
Expiration Date	July 2017

Click in the *REPAIR BOX* while completing your claim on BOSSWeb.



The screenshot shows a web interface with a dark header. Below the header, there is a section titled ***Action**. Under this title, there are two options: **Inspect** and **Repair**, each with a corresponding checkbox. A large black arrow points to the **Repair** checkbox. Below these options is a button labeled **Upload File**. At the bottom left of the screenshot, the text **mbg2012-010-004_ben** is visible.