

Classification:

GI15-002

Reference:

ITB15-013

 COPYRIGHT© NISSAN NORTH AMERICA, INC.
 Date:

March 12, 2015

PC358 IS LISTED IN SERVICE COMM

APPLIED VEHICLES: Check Service COMM for PC358 eligibility.

INFORMATION

If this bulletin applies by checking Service COMM (PC358).

AND

The TCM's current part number is listed in **Table A** below.

THEN

Reprogram the TCM.

NOTE: If you are not familiar with the reprogramming procedure, [click here](#). This will link you to the "CONSULT- III plus Reprogramming" general procedure.

Table A

Current TCM Part Number Before Reprogramming: 31036 -	
9NA6A, 9NA6B, 9NA6C, 9NA6D, 9NA6E 3JU0A, 3JU0B, 3JU0C, 3JU0D, 3JU0E, 3JU1A	9NA7A, 9NA7B, 9NA7C, 9NA7D 3JU3A, 3JU3B, 3JU3C, 3JU3D

CLAIMS INFORMATION

Submit a CM line claim using the following claims coding:

CM I.D. #	DESCRIPTION	OP CODE	FRT
PC358	Reprogram CVT Transmission	PC3580	0.6 hrs.
	TCM Part Number not in Table A – No Reprogram Required	PC3581	0.3 hrs.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.