



SERVICE BULLETIN

Classification: GI15-001	Reference: NTB15-016	Date: March 12, 2015
-----------------------------	-------------------------	-------------------------

PC357 IS LISTED IN SERVICE COMM

APPLIED VEHICLES: Check Service COMM for PC357 eligibility.

INFORMATION

If this bulletin applies by checking Service COMM (PC357).

AND

The TCM's current part number is listed in Table A below.

THEN

Reprogram the TCM.

NOTE: If you are not familiar with the reprogramming procedure, **click here**. This will link you to the "CONSULT- III plus Reprogramming" general procedure.

Table A

Current TCM Part Number Before Reprogramming: 31036 -	
3KD2A 3KD4A, 3KD4B, 3KD4C, 3KD4D, 3KD4E 3KD5A, 3KD5B, 3KA2A	3KA4A, 3KA4B, 3KA4C, 3KA4D, 3KA4E 3KA5A, 3KA5B 9PA7A, 9PA7B, 9PA7C, 9PA7D 9PA3A, 9PA3B, 9PA3C, 9PA3D

CLAIMS INFORMATION

Submit a CM line claim using the following claims coding:

CM I.D. #	DESCRIPTION	OP CODE	FRT
PC357	Reprogram CVT Transmission	PC3570	0.6 hrs.
	TCM Part Number not in Table A – No Reprogram Required	PC3571	0.3 hrs.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.