



SERVICE BULLETIN

Classification:

HA15-006

Reference:

NTB16-010

Date:

January 19, 2016

2014 TAXI; A/C CONDENSER LEAK NEW RADIATOR CORE SUPPORT

APPLIED VEHICLES: 2014 Taxi

IF YOU CONFIRM

The A/C condenser has a crack and leak in the area shown in Figure 1.



Figure 1

ACTION

Replace the A/C condenser and the radiator core support lower.

- The radiator core support lower is shown in Figure 2 on the next page.
- Use the new radiator core support lower listed in the Parts Information.
- Refer to the Electronic Service Manual (ESM) for replacement information.
 - For the condenser; ESM section HA – Heater & Air Conditioning System
 - For the radiator core support lower; ESM section DLK – Door and Lock

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.




Figure 2

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
A/C Condenser	92100-3LM0A	1
Radiator Core Support Lower	F2530-3LMAA	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL A/C Condenser	92100-3LM0A	TD10AA	GB	53	(1)
Evacuate/Recharge - R134A Systems only		TB777A			
Replace Radiator Core Support Lower		UE65AA			

(1) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.

Expense code:

EXPENSE CODE	DESCRIPTION	MAX AMOUNT
010	R134A REFRIGERANT	(2)

(2) Claim the actual amount needed to recharge the A/C system.