

Measure no.

US 61526277-01

Subject

Grab handles installed in place of luggage rack

Status date (mm/dd/yy)

6/3/15

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

6/3/15

Created by

Christine Koehling

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K49

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

S 1000 XR was ordered with luggage rack but delivered with grab handles.

Cause

Due to quality issues with the surface coating on the luggage rack, there is an insufficient supply.

Measure

So vehicle deliveries are not delayed unnecessarily, some vehicles are being delivered with grab handles in place of luggage racks. An information sheet is included with vehicles that were ordered with a luggage rack and delivered with grab handles.

Racks which meet the quality standards of BMW Motorrad are expected to be available mid-July (week 29).

A Service Information Bulletin will be posted as soon as a sufficient quantity of parts are available.

Complaint**Fault location**

46/54 Luggage carrier

Fault type

Missing, missing part

Fault place

Cause

| # | Fault location | Fault type | Fault place |
|-------------|-----------------------|------------------------|-------------|
| 1 | 46/54 Luggage carrier | Surface coating not OK | |
| Repair Task | Special Clearance | Area | |
| Other tasks | No | Body and Trim | |

Fault code

Progman / DIS / ISTA / ISTAP

| System | State | Version |
|--------|-------|---------|
|--------|-------|---------|

© 2002-2015 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.