

**Measure no.**

US 61737415-01

**Subject**

Side covers come loose

**Status date (mm/dd/yy)**

7/2/15

**Status**

Accepted

**Organization**

US, MOT

**Date created (mm/dd/yy)**

7/2/15

**Created by**

Christine Koehling

**PQM Problem reference****Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

**Vehicles affected****E series**

K52

**Engine****Body****Production period (from/to)**

(mm/dd/yy)

**Comment on production period**

/

**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

The spring strut cover 46 63 8 534 860 on the left and the handwheel cover 46 63 8 534 861 on the right come loose very easily when the motorbike is being ridden.

**Cause**

The cover mounting is too loose. They come out of the rubber mounting easily due to the air stream. Pictures\_01 and \_02 show the covers fitted and when they have been removed.

**Measure**

It is crucial that the covers are fitted correctly. When fitting them, it is important to take extra care to ensure that all the studs have been pushed in their rubber mounts properly. If any of the studs have not been properly pushed in, the panel in question will be loose.

**Complaint****Fault location**

46/63 Trim panel, rear,  
battery trim

**Fault type**

Part connection: Loose

**Fault place**

Both sides / all

---

**Cause**

#	Fault location	Fault type	Fault place
1	46/63 Trim panel, rear, battery trim	Part connection: Loose	Both sides / all
Repair Task	Special Clearance	Area	
Remove and install	No	Body and Trim	

---

**Fault code**

---

**Progman / DIS / ISTA / ISTAP**

System	State	Version
--------	-------	---------

---

© 2002-2015 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.

