Technical Bulletin



SERVICE BULLETIN Classification: Reference: Date: EL15-043 NTB15-116 December 22, 2015

2016 TITAN XD DIESEL; BATTERY DISCONNECT WAIT TIME / DTCS P2509 & P181B


APPLIED VEHICLES: 2016 Titan XD (A61)

APPLIED ENGINE: Cummins 5.0L Turbo Diesel

SERVICE INFORMATION

When disconnecting either of the 12 volt batteries on the Titan XD Diesel, follow these steps:

- 1. Turn the ignition OFF.
- 2. Wait at least 2 minutes.
- 3. Disconnect battery (negative cable first).



NOTE:

- If the above steps are not followed, DTCs P2509 and P181B may be stored.
- If these codes are stored because the battery disconnection was done without waiting 2 minutes, they can be cleared, but it is not a warrantable repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.