

# SERVICE BULLETIN



M-1418

December 10, 2015

## MIDTRONICS GRX 3110 HD BATTERY DIAGNOSTIC STATION AND THE NEW SPORTSTER BATTERY

### Purpose

The Midtronics GRX 3110 HD Battery Diagnostic Station does not recognize the new Sportster battery (Part No. 65958-04B). This bulletin describes what action is necessary until a new GRX 3110 HD software update is available.

### Vehicles Affected

This service bulletin applies to all 2016 Sportster models. Earlier model year Sportsters will get the new battery upon battery replacement.

### Markets Affected

This service bulletin affects all markets where the 2016 Sportster is sold.

This service bulletin affects all markets where the battery (Part No. 65958-04B) is sold as a replacement battery.

### Required Dealer Action

The Midtronics GRX 3110 HD Battery Diagnostic Station will charge and service the new battery (Part No. 65958-04B) if the old battery part number (Part No. 65958-04A) is used. Use the old battery part number when initializing a warranty check.

A new software revision will be made available to address this change.

#### NOTE

*In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.*

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

© 2015 H-D