



## Service Bulletin

---

### E112

---

#### Section

Inlet / Exhaust - DEF

---

#### Description

Software Update for DEF Decomposition Pipe Fault

---

#### Release Date

5/11/2015

---

#### Introduction

##### **This is a Fix as Fail Repair**

Peterbilt has determined on vehicles manufactured with a PACCAR MX-13 EPA 2013 model year 2013 or 2014 engine, that certain DEF decomposition pipes may not promote adequate DEF mixing, thereby leading to overdose and NH3 (Ammonia) slip, which in turn can trigger fault code P3818.

---

#### Resolution

If a customer enters your dealership and is experiencing the fault code P3818 on an affected chassis, update to the most current version of software.

**Note: Decomp pipe replacement with high route exhaust is no longer required if an engine is flashed with the most current software update.**

---

#### Warranty

Through Standard Warranty (includes Extended Warranty) and Emissions Warranty (5 years/100k miles) Peterbilt will pay for parts plus applicable mark up and labor to update MX engine software on vehicles presented with fault code 3818.

File claims using Quick Claim **E112** when flashing engines to resolve fault code P3818.

Quick Claims cannot be used when filing claims for service performed on Kenworth Vehicles. Use the long claim input form in DWWC by selecting **Draft/Offline Claims, General** tab, and in the **Type of Claim** drop down box, select PACCAR Engine Claim. Use the claim codes listed below **AND** send an e-mail to [PBDiv.CS.Campaigns@PACCAR.com](mailto:PBDiv.CS.Campaigns@PACCAR.com)

with the chassis # and Campaign # in the subject field:

- File a long claim for additional labor after a quick claim has been submitted for other extraordinary circumstances (which must be explained).

For Field...	Enter...
Failure Location	043-007-148
Failure Type	700
Claim Type	A
SRT 045-986	0.3 Hours Labor to update software
SRT 045-988	0.3 hours Labor (15 min wait)

---

## Parts

There are no parts for this bulletin, only software updates.

---

## Labor

Peterbilt will pay for 0.6 hours labor for download and updating the software.

---

## Procedure

Connect vehicle to DAVIE4 and update PRS file

**Update to the most current software version to resolve Fault Code P3818 on MX-13 model year 2013 and 2014 MX-13 engines.**

---

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2015 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).