

10/14/15

MY15 WD

GPOP - Issue Review System

Part Number: L0003157\$\$

Part Description: Turn Signal Bulb

Issue Description: If the filament is broken proceed as normal for the parts return process. If the filament is not broken and does not function follow the process listed in this bulletin. If the customer complaint is (bulb inoperative) please change the bulb L0003157NAK and socket P/N 68224606AA and return together to the Quality Engineering Center (QEC) for analysis. It is very important to have both bulb and socket together for traceability. Email the last 8 of the VIN, mileage and send the part to the QEC.

Contact Ryan Lucas- cell (248) 421-9535 ryan.lucas@fcagroup.com, if you have further questions.

~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
