

NUMBER: 14-001-15

GROUP: Fuel System

DATE: February 17, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-008. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Diesel Fuel Filter Weepage in Extreme Cold Conditions

OVERVIEW:

This bulletin involves installing a new fuel/ water separator filter.

MODELS:

2014 - 2015 KL

Jeep Cherokee (International Only)

NOTE: This bulletin applies to vehicles built on or before December 1, 2014 (MDH 1201XX) equipped with 2.0L I4 Turbo Diesel Engine (Sales Code EBT) and Russia Country Code (Sales Code 8FE) or Sweden Country Code (Sales Code 8F6) or Finland Country Code (Sales Code 8CA) or Norway Country Code (Sales Code 8EW).

SYMPTOM/CONDITION:

Diesel fuel weepage from bottom of the vehicle when a cold soaked vehicle is started at temperatures of -13 F (-25 C) or below when using artic diesel fuel or a cold weather diesel fuel additive.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68110234AB	Fuel Filter / Water Separator

14-001-15 -2-

REPAIR PROCEDURE:

1. To replace the Fuel Filter / Water Separator refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 14 - Fuel System> Fuel Delivery, Diesel - Separator and Filter, Fuel and Water.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
14-40-01-98	Replace Fuel Filter / Water Separator (1- Semi-Skilled)	10 - Diesel	0.5 Hrs.

FAILURE CODE:

ZZ	Service Action	
----	----------------	--