



15671A - Service Update - Excessive Wiring Harness Length - Revised Service Procedure
Updated Date: Jan 22, 2016 14:50 ET

GM CUSTOMER CARE AND AFTERSALES
DCS3902
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 22, 2015

Subject: 15671A - Service Update Bulletin
Excessive Wiring Harness Length
Revised Service Procedure

Models: 2015 Chevrolet Colorado
2015 GMC Canyon
Equipped with 3.6L V6 Engine (RPO LFX)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

This bulletin is being revised to update Step 1 of the Repair Procedure in the Service Procedure section. Please discard all copies of bulletin 15671.

GM CUSTOMER CARE AND AFTERSALES



15671A Bulletin.pdf

About this Alert

Reference Number: GCUS-3-412
Published to: Home Page
Version: 1.0
Alert Type: Service Update
Original Published Date: Jan 22, 2016 14:50 ET
Expires: Mar 22, 2016 0:00 ET
Contact : loren.rusk@gm.com