



Service Bulletin

File in Section: 02 - Steering

Bulletin No.: 09-02-36-001A

Date: January, 2015

TECHNICAL

Subject: Inconsistent Power Steering Assist, Intermittent DTC C0545 Set In Power Steering Control Module (Diagnose and Repair Using SI)

Models: 2009 Chevrolet Malibu
2009 Pontiac G6
2009 Saturn AURA
Equipped with Engine RPO LE5
Built February 2, 2008 Through March 3, 2008
Please Refer To GMVIS

This Bulletin has been canceled. Please discard Corporate Bulletin Number 09-02-36-001.

This bulletin is no longer valid. If you encounter a vehicle with this concern, please refer to published diagnostic information and procedures for DTC C0545 found in SI.