



# Service Bulletin

File in Section: -

Bulletin No.: PIP5258

Date: February, 2015

## PRELIMINARY INFORMATION

**Subject:** SES Lamp With Camshaft Actuator Codes After SI Diagnosis Have Been Followed

**Models:** 2007 - 2013 Cadillac Escalade, Escalade Hybrid  
 2007 - 2013 Chevrolet Avalanche, Express, Silverado, Silverado Hybrid, Suburban, Tahoe, Tahoe Hybrid  
 2007 - 2013 GMC Savana, Sierra, Sierra Hybrid, Yukon, Yukon Hybrid  
 With V-8 engine  
 4.8L L20  
 5.3L LC9 LMF LMG  
 6.0 L76 L96 LC8 LY6 LZ1  
 6.2 L9H

This PI was superseded to make eternal.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A vehicle may be brought to the dealer with the SES on, setting a P0011 DTC

### Recommendation/Instructions

If SI has been followed without a fix, the following information may be helpful.

1. Check the oil pressure at the oil pressure sender.
2. Check the number 2 cam bearing. (This is the location the oil is feed from to the actuator).

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4064690	Camshaft Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.