



# Service Bulletin

File in Section: -

Bulletin No.: PIC6063

Date: February, 2015

## PRELIMINARY INFORMATION

**Subject:** Unwanted Activation Of Park Assist Warning

**Models:** 2015 Cadillac CTS Sedan VIN A  
2015 Cadillac XTS  
With Advanced Park Assist (APA) (RPO UFQ)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer may comment that their park assist warning goes off with nothing around the vehicle. It may be found that the DIC will display the park assist warning along with a chime or haptic seat activation with objects that are out of the normal range of the park assist sensors.

### Recommendation/Instructions

**Important:** IMPORTANT: Do NOT replace parts for this issue.

Engineering is aware of this concern and is working on a software change for this issue.

This PI will be updated when the software becomes available.

### Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

### ADDITIONAL SI KEYWORDS:

activation calibration program seat vibration

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.