

Service Campaign Bulletin

SB-10058143-3332



Mercedes-Benz

Campaign No. 2015040001, April 2015

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 222 (S-Class), Model Year 2015**
Replace Blower Motor

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that the blower motor does not correspond to current specifications. The electrical line of the blower motor may chafe at the stator and thus generate noises. The blower may also fail due to the chafed-through line. To correct this condition an authorized Mercedes-Benz dealer will replace the blower motor at the next dealer visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 225 vehicles are affected.

Order No. P-SC-2015040001

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin


Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

1.  Replace blower motor, refer to WIS: AR83.10-P-1100LF.

 Note (regarding above WIS instructions):

Do not remove trim piece from left side of dash board.

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Blower motor	A 222 820 2214	100%

 Note:

- Please be aware that only the part number(s) referenced in the Campaign Bulletin is/are approved for use to repair the vehicle. Repairs performed using any other part(s) will not have been performed in accordance with the campaign. Accordingly, warranty claims submitted with reference to an improper part number(s) will be denied.
- The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Replace blower motor for heater (02-8840).

Damage Code	Operation Number	Labor Time (hrs.)
83 900 38 7	02-8840	1.0

 Note

Operation Number labor times are subject to change.