

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR MARCH 2015

45007 2015 Expedition, Navigator, F150 With MY FORD TOUCH Or MY LINCOLN TOUCH -
Climate Controlled Seat Buttons - Improper Operation

Some 2015 Expedition, Navigator, and F150 vehicles built with MFT or MLT and Climate Controlled Seats (CCS) may have a concern of unintended CCS operation while operating another mode on the 8+ touch screen or while using any climate control buttons in the Front Controls Interface Module. This symptom usually occurs if a touch screen CCS button is initially pushed and another button is pressed simultaneously. This may also occur if the operator touches another area of the touch screen in conjunction with the CCS buttons. To exit from this state the user needs to touch another one of the CCS buttons without touching another location on the touch screen or dragging their finger upon release. Engineering is currently investigating this concern. No other repairs should be attempted at this time. Monitor OASIS for future updates.