

SB-10058196-7186

## ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR MARCH 2015

44986 2008-2012 Escape/Mariner - With DTC B2278 In Power Steering Control Module (PSCM) - Steering Column Replacement Is Not Required

Some 2008-2012 Escape/Mariner vehicles may exhibit DTC B2278 stored in the PSCM. When this DTC is present the torque sensor must be replaced. Torque sensor part number CL8Z-3F818-A is a serviceable component and the steering column assembly does not require replacement. The WSM is currently being updated to include the removal and installation procedure and enhanced diagnosis and testing section. This is expected to be complete by early April 2015. In the meantime, the removal and installation instructions are included with new torque sensor kits and it is also available in Attachment III technical instructions of safety recall 14S05. In addition it is also recommended to review the torque sensor installation video located under Service Tips on PTS. Please continue to monitor OASIS for updates.