

SB-10058200-7932

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MARCH 2015**

44960 2015 Transit High Roof Bus/Wagon Vehicles Headliner That Does Not Stay Seated

Some 2015 Transit High Roof Bus/Wagon vehicles may have a headliner that does not stay seated at the C and/or C and half pillar hard trim. This concern is currently under investigation by engineering. Do not attempt repairs at this time. Monitor OASIS for updates to this concern. Note: Headliner retention in these areas is intentionally delicate to allow for proper air curtain deployment - visual inspection is adequate for this condition, while physical tugging or prying may damage an otherwise acceptable connection.