

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MARCH 2015**

- 45006 2008-2012 Escape/Mariner - With DTC B2278 In Power Steering Control Module (PSCM) - Steering Column Replacement Is Not Required

Some 2008-2012 Escape/Mariner vehicles may exhibit DTC B2278 stored in the PSCM. When this DTC is present the torque sensor must be replaced. Torque sensor part number CL8Z-3F818-A is a serviceable component and the steering column assembly does not require replacement. The Workshop Manual has been updated to include the revised diagnostic path for DTC B2278 and the torque sensor removal and installation procedure. In addition, the removal and installation instructions are included with new torque sensor kits. It is recommended to review the torque sensor installation video which is located under Service Tips and also in the WSM removal and installation procedure on PTS.