

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MARCH 2015**

45021 2015 Fusion S And SE - Unable To Reset Engine Oil Life - Built On Or Before 12/15/2014
- IPC Update Available

Some 2015 Fusion S and SE vehicles built on or before 12/15/2014 that are not equipped with MyFord Touch may not be able to reset the Engine Oil Life using the instrument cluster reset procedure. To correct the concern, update the Instrument Panel Cluster (IPC) to the latest calibration using IDS version 93.02 or higher. Make sure you are connected to the internet when entering module programming to guarantee you are receiving the latest updates. Use applicable 12651D labor operations from section 10 of the SLTS manual, and use 10849 as the causal part.