

SB-10058450-1661

ONLINE AUTOMOTIVE SERVICE INFORMATION FOR MAY 2015

45120 2015 F-150 3.5L GTDI - Loss Of Power And DTC P0299

Some 2015 F-150's equipped with the 3.5L GTDI engine may exhibit a loss of power and DTC P0299. Before beginning diagnostics, inspect the Intake Tube at the Throttle Body for proper retention and positioning. The proper torque of the Intake Tube should be 5.4Nm (48 lb-in). If the Intake tube is secure, refer to PC/ED for normal diagnosis.