

## TECHNICAL BULLETIN

LTB00774NAS1

21 JUL 2015

**SB-10058470-5943**

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

**SECTION: 211-04**

## Heated Steering Wheel Not Operating Correctly

**AFFECTED VEHICLE RANGE:****Range Rover Sport (LW)****Model Year:** 2014-2015**VIN:** 000001-519362**Manufacturing Plant:** Solihull**Range Rover Sport (LW)****Model Year:** 2014-2015**VIN:** 600000-615620**Manufacturing Plant:** Solihull**Range Rover (LG)****Model Year:** 2013-2015**VIN:** 000001-216716**Manufacturing Plant:** Solihull**MARKETS:**

NAS

**CONDITION SUMMARY:****Situation:** The Heated Steering Wheel (HSW) may operate when not requested.**Cause:** This may be caused by a software error in the Steering Wheel Heater Control Module (SWH).**Action:** Should a customer express this concern, follow the Service Instruction outlined below.**PARTS:**

LR077225	Steering wheel electrical wiring harness - Without paddle switches	Quantity: 1
LR077224	Steering wheel electrical wiring harness - With paddle switches	Quantity: 1

**TOOLS:**

Refer to Workshop Manual for any required special tools.

SECTION: 211-04

**WARRANTY:**

**NOTE:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.