



SI B27 01 15
Intermediate and Special Transmission

March 2015
Technical Service

PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS.

SUBJECT

Service Action: Replace Park Lock Actuator

MODEL

I01 (i3)

SITUATION

Unfavorable tolerances in the park lock actuator may lead to a functional failure or unusual noises when it is activated. As a result, the park lock actuator must be replaced on affected vehicles.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

AFFECTED VEHICLES

This Service Action affects certain I01 vehicles produced from February 11, 2014 through February 17, 2014.

First check if a Service Action label with a code number **732** is already attached to the A-pillar.

If a code number **732** has been punched out, the Campaign has already been performed and no further action is necessary.

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

PROCEDURE

Only properly trained personnel, who have passed all applicable technical training courses, should perform any maintenance or repairs on any Hybrid or Electric Vehicle. Work performed by unqualified persons may result in severe injury or damage to the vehicle. Additional information may be found in REP 61 00... Observe safety instructions when handling electric vehicles.


- Replace the park lock actuator per REP 27 21 315.

PARTS INFORMATION

Part number	Description	Quantity
27 21 7 645 837	Park lock actuator	1

LABEL INSTRUCTIONS

	<p>This Service Action has been assigned code number 732. After the vehicle has been checked and/or corrected, obtain a label (SD 92-464) and:</p> <p>A. Emboss your BMW center warranty number in the middle of the label (1);</p>
--	--



- B. Punch out code number **732 (2)**, printed on the label; and
- C. Affix the label to the A-pillar as shown.

If the vehicle already has a label from a previous Service Action/Recall Campaign, affix the new label next to the old one. Do not affix one label on top of another one because a number from an underlying label could appear in the punched-out hole of the new label.

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code:	00 27 06 01 00	
Labor Operation:	Labor Allowance:	Description:
00 62 922	Refer to KSD2	Replace park lock actuator – BEV only (Includes performing a vehicle test).

Labor operation code 00 62 922 is a Plus labor operation.

[Copyright ©2015 BMW of North America, Inc.]