

SB-10058594-4221

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR AUGUST 2015**

45270 2015-2016 F-Super Duty Vehicles Equipped With 6.7L Diesel - Runs Rough During Exhaust Regeneration Process - Updated Calibration Due 1Q 2016

Some 2015-2016 F-Super Duty pickups equipped with 6.7L diesel engines may exhibit a runs rough condition during exhaust regeneration. This condition may occur when the vehicle is idled for prolonged periods of time or when frequently driven short distances that don't allow the regeneration cycle to complete. A calibration to address this concern is expected to be available in late March 2016. For customers that insist on a repair it is allowable to perform TSB 15-0124 until the calibration TSB becomes available. To avoid a repeat occurrence customers need to be reminded to follow the drive cycle recommendations in the Customer Information Sheet that is included with TSB 15-0124.