

SB-10058600-5315

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JULY 2015

45210 2014-2016 Fusion Titanium Hybrid And Titanium Energi - Reduced Subwoofer Volume in Electric Vehicle (EV) Mode

Some 2014-2016 Fusion Titanium Hybrid and 2014-2016 Fusion Titanium Energi vehicles equipped with Sony Premium Audio may exhibit a concern of decreased subwoofer performance or decreased subwoofer volume when the gas engine turns off or when the vehicle is in EV mode. To correct the concern update the Audio Digital Signal Processing module (DSP) to the latest calibration using IDS version 96.02 or higher. Calibration files may also be obtained at www.motorcraft.com. Use applicable 18805D labor ops from Section 11 of the SLTS manual and use causal part 18A849 for reprogram.