

## **SB-10058603-4940**

### **ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JULY 2015**

45214 2014 Focus - Distance To Empty (DTE) Drops Too Fast While Driving Then Increases Back To Expected Value After An Ignition Cycle

Some 2014 Focus vehicles may exhibit a concern of the Distance To Empty (DTE) indication dropping too fast while driving, then increasing back to the expected value after parking the vehicle and later restarting the engine. To improve the DTE accuracy reprogram the Body Control Module (BCM) to the latest calibration using IDS release 96.02 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at [www.motorcraftservice.com](http://www.motorcraftservice.com). For warranty claiming use causal part 14A068 and use applicable 12651D labor operations in SLTS manual Section 10.