

## **SB-10058608-9653**

### **ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JULY 2015**

45221 2015 F-150 - Door Fitment Job Aid Video And Door Fitment Worksheet Available On Professional Technician Society Website

Some 2015 F-150 vehicles may exhibit customer concerns of excessive wind noise isolated to the door area, difficult to close door(s) and/or door panel margins and flushness gap fitment issues. To assist with obtaining the correct body margin measurements, refer to the 2015 F-150 Door Fitment Job Aid Video and the 2015 F-150 Door Fitment Worksheet located on the Professional Technician Website (PTS) in the General Communications section under the Service Tips tab. Refer to the Workshop Manual (WSM) Section, 501-26 to obtain the body margin and flushness specifications. The body alignment procedures in WSM Section, 501-03 can be used to make any adjustments required to resolve the customer concern. Use applicable labor operations from Section 12 of the Service Labor Times Standards.