

SB-10058610-3063
ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR JULY 2015

45223 2016 MKX - Interior A-pillar Trim Panel Not Seating Properly Under The Front Door Weatherstrip

Some 2016 MKX vehicles may exhibit an issue where the interior A-pillar trim panel may not stay seated under the front door weather strip where the A-pillar trim panel and headliner meet. Reseating the A-pillar trim panel may provide temporary resolution. Engineering is investigating the concern and no repairs should be attempted. Monitor GOASIS for updates.