

SB-10058618-2904

45289 2014-2015 Fiesta With Automatic Transission Engine Oil Minder - Oil Change Now Indicator Message Inoperative - Built On Or Before 06/01/2015 - Update Available

Some 2014-2015 Fiesta with automatic transmission vehicles built on or before 6/11/2015 may exhibit an oil change now indicator message that is inoperative. Ensure that FSA 15B22 has been performed. This calibration includes an update to the PCM which will resolve the concern. For vehicles equipped with a 1.0 GTDI the ICP will need to be reprogrammed also. Refer to section 10 of the service labor time standard for appropriate labor times.