

SB-10058631-6630

45295 2013-2016 Escape - Glovebox Door Misalignment Due To Right Or Left Side Catch/
Striker Assembly Coming Loose

Some 2013-2016 Escape vehicles may exhibit a concern with glovebox door misaligned/loose on the right or left side due to the glovebox catch/striker coming loose. This part is available as a separate service component. The entire glovebox assembly does not need to be replaced. If a vehicle comes in for this condition, order part number CJ5Z-9906064-AB (RH) or CJ5Z-9906064-AA(LH).