

SB-10058661-9488

45309 2015-2016 MKZ, 2015 MKC - Missing Artist/Title/Track Information In The Instrument Cluster Message Center

Some 2015-2016 MKZ and 2015 MKC vehicles may exhibit a concern with missing Artist/Title/Track information in the instrument cluster message center. Reprogram the Instrument Panel Cluster (IPC) module to the latest calibration using IDS release 96.05 or higher. Make sure you are connected to the Internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at www.motorcraftservice.com. Use causal part 10849 and use applicable 12651D labor operations in section 10 of the SLTS manual.

45310 2015-2016 F150, Ford Focus and Mustang - Instrument Wheel Speed (WSP) Concern