

## GPOP - Issue Review System

**Part Number:** 68140678A\$

**Part Description:** Crankshaft Position Sensor

---

**Issue Description:** Before replacing this part due to a P0335 fault code, please contact Mitch Deperno at cell (248) 882-9869. Engineering is interested in the condition(s) present when the fault occurs.~

If no response is received within 15 minutes, then continue with repair.~

Also, if possible, please send Freeze Frame data and Mark Sync Event data to [mitch.deperno@fcagroup.com](mailto:mitch.deperno@fcagroup.com).~

To Retrieve Marks Data on WiTech:~

1) Choose "Monitors" and select "OBDII Monitors" from the drop down box.~

2) At the next Screen, choose "Cam Crank Synchronization Monitor".~

3) Once you select the Cam Crank Synchronization event Monitor, you will get to the three pages of Marks Event Data.~

If no response is received within 15 minutes, then continue with the necessary repair.

~\_\_\_\_\_~

Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---