

SB-10058974-6539



SI B09 05 15
Programming/Coding Explanations

July 2015
Technical Service

SUBJECT**Front Parking Lights Inoperative****MODEL**

F30 (3 Series)

F31 (3 Series Sports Wagon)

Vehicles produced up to June 30, 2015

SITUATION

After programming the vehicle with ISTA/P 3.56.1, both front parking lights (integrated in the headlights) have been deactivated and no Check Control message is displayed.

CAUSE

FEM software error in ISTA/P 3.56.1

PROCEDURE

Solution is planned to be released with ISTA/P 3.56.2.004

Until ISTA/P 3.56.2.004 becomes available, **do not** carry out any programming or coding on the affected vehicles.

In critical cases where programming and coding needs to be performed, please submit a PuMA case titled "F30: Park light INOP". Once we receive the PuMA case, we will provide you with further instructions.

ISTA/P 3.56.2.004 will be released on Monday, August 3, 2015, I-Level F020-07-503. When the update software is loaded, you can resume using ISTA/P to program the affected vehicles.

[Copyright ©2015 BMW of North America, Inc.]