

SI B11 11 15 Engine August 2015 Technical Service

This Service Information bulletin supersedes SI 11 11 15 dated June 2015.

NEW designates changes to this revision

SUBJECT Service Action: Replace the Thermostat

MODEL F10 (5 Series Sedan)

SITUATION

The Service Engine Soon light is on with corresponding fault codes in the DME for the engine thermostat.

AFFECTED VEHICLES

This Service Action involves certain F10 vehicles produced from February 2011 to March 2014.

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

PROCEDURE

Replace the engine thermostat. Follow Repair Instruction RS 11 53 000, "Removing and installing/replacing coolant thermostat (N20, N26)."

PARTS INFORMATION

P/N 11 53 8 657 053, as specified and listed in this Service Information bulletin below, must be ordered and installed for this Service Action.

Performing a part number look-up in ETK by VIN or model will result in the wrong part being invoiced and installed.

The part number in ETK will not satisfy completion of this Service Action.

Part Number	Description	Quantity
11 53 8 657 053	Thermostat	1

WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

Defect Code: 00 11 58 03 00

Completion before vehicle delivery to the customer or the vehicle is already in the workshop

Labor Operation:	Labor Allowance:	Description:

00 62 940	Refer to KSD2	Replace the
		thermostat (Plus
		work – without the
		"Service Engine
		Soon" light on)

Or:

Labor Operation:	Labor Allowance:	Description:
00 63 540	Refer to KSD2	Replace thermostat (includes connecting an approved battery charger/power supply and performing a vehicle test) (Plus work - with the "Service Engine Soon" light on)

Or:

Completion after vehicle delivery to the customer

Labor Operation:	Labor Allowance:	Description:
00 63 015	Refer to KSD2	Replace thermostat (includes connecting an approved battery charger/power supply and performing a vehicle test) (Main work - with the "Service Engine Soon" light on)

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance.

And:

NEW Sublet - Coolant

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for "replacing the drained quantity" of antifreeze/coolant (BMW bulk container). Please do not use the BMW part number for claim submission.)
---------------	--	--

Sublet calculation: Reimbursement for "replacing the drained quantity" of antifreeze/coolant at dealer net plus handling.

Enter this material cost in sublet and itemize the amount of coolant that had to be replaced in the claim comment section.

Note: The BMW gallon bulk container (P/N 82 14 1 467 704) provides two gallons when mixed with water to create 50/50 mixture)

ADDITIONAL INFORMATION

Perform the procedure outlined in this Service Information on all affected vehicles before customer delivery or the next time they are in the shop for maintenance or repairs.

[Copyright ©2015 BMW of North America, Inc.]