

**SUBJECT****Service Action: Reprogram the DDE****MODEL**

E70 (X5)

With the M57Y engine

**SITUATION**

The DDE calibration for readiness monitoring may be incorrect.

**AFFECTED VEHICLES**

This Service Action involves E70 vehicles with the M57Y diesel engine produced from August 10, 2010 to June 22, 2013.

Vehicles which require this Service Action to be completed will show it as "Open" when checked either in the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

**PROCEDURE**

Program the vehicle using ISTA/P 2.49.3 or a more recent version.

Target integration level: E070-13-03-504

Note that ISTA/P will automatically reprogram and code all programmable control modules that do not have the latest software.

For information on programming and coding with ISTA/P, refer to Centernet / Aftersales Portal / Service / Workshop Technology / Vehicle Programming.

**WARRANTY INFORMATION**

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

<b>Defect Code:</b>	<b>00 13 37 02 00</b>	
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 63 594	1 FRU	Programming and coding in conjunction with another campaign or repair (vehicle is already at the specified "Target" integration level or higher, no repair is necessary)
Or:		
00 63 595	8 FRU	Program and encode the control units (not including CAS) (Includes a vehicle

		test and charging the battery)
Or:		
00 63 596	9 FRU	Program and encode the control units (including the CAS) (Includes a vehicle test and charging the battery)

The labor operations codes listed above are “Plus” labor operations.

**ADDITIONAL INFORMATION**

Perform the procedure outlined in this Service Information on all affected vehicles before customer delivery or the next time they are in the shop for maintenance or repairs.

[ Copyright ©2015 BMW of North America, Inc. ]