

**SB-10059034-6501**



## Service Bulletin

File in Section: -

Bulletin No.: PIE0334A

Date: August, 2015

# PRELIMINARY INFORMATION

**Subject:** Engineering Information – Hard to Steer Vehicle When Cold

**Models:** 2013-2015 Buick Encore  
2014-2015 Chevrolet Trax

**This PI has been revised to end the need for information from the field.  
Please discard PIE0334.**

If you encounter a vehicle with this condition, please refer to published diagnostics and repair procedures in SI.